

📍 Office Corner
Block C, 184 Lancaster Road,
Gordon's Bay,
7140

☎ 066 105 1226
✉ techq.development@outlook.com
📠 086 474 1937

🌐 www.techq-development.com



Ref: DM2025 – WC – SE - 041

Professional Engineering Services

Structural Engineering Investigation to the property
on Erf 3126, Hartenbos
House Venter

Report – Rev 0

15 October 2025

Contact Person: **Melt Badenhorst** (Pr.Tech.Eng)(Pr.CPM)

Document Control Sheet

Client Project Reference DM2025 – WC – SE - 041		Internal Project Number TechQ – 041	
Title Structural Engineering Investigation to Erf 3126 Hartenbos			
Project Stage Investigation and Concept Remedial Proposals			
Version	Date	Comment	
Rev 0	15 October 2025	Report submitted for review.	
Prepared For: The Project Manager National Home Builders Registration Council 27 Leeuwkop Road, Sunninghill Johannesburg 2191			
Prepared By: TechQ Development (Pty) Ltd OFFICE CORNER – Block C 184 Lancaster Road Gordon's Bay 7140			
Compiled By: Consultant  MJ Badenhorst (Pr.Tech.Eng) (Pr.CPM) ECSA : Pr. Reg No. 200270009 NHBRC : 601551		Reviewed By: (Client – NHBRC)  Dalitso Mkandawire (Pr.Eng) Provincial Engineer - WC 15 October 2025	
			

Table of Contents

EXECUTIVE SUMMARY	1
1 PROJECT LOCALITY, SCOPE AND INFORMATION	2
1.1 Project Locality	2
1.2 Scope of Work	2
1.2.1 Original RFQ scope of works	2
1.2.2 Additional scope following site brief and site inspection.....	2
1.3 Information Provided and Independent tests conducted	2
1.3.1 Annexure B – Municipal approved Architect drawings	2
2 INVESTIGATION: DISCREPANCIES, NON-CONFORMANCES AND POSSIBLE ROOT CAUSES	3
2.1 Defected metal roof of Patio Balcony	3
3 ENGINEERING REMEDIAL SOLUTIONS AND RECOMMENDATIONS	3
3.1 Reconstruct Patio balcony roof section.....	3
3.2 Repair roof flashing, ceiling boards and straps	4
3.3 Summary: Engineering Solutions.....	4
4 RISKS & MITIGATION MEASURES	4

Annexures

- A - Drawing No. HVenter – Struct 01
- B - Municipal approved Architect drawings – Jun 2019

EXECUTIVE SUMMARY

This **Structural Engineering and Waterproofing Investigation Report** is presented by **TechQ Development (Pty) Ltd** based on the *Request for Proposals (RFP)* called by the **National Home Builders Registration Council (NHBC)** in terms of the *Housing Consumer Protection Measures Act (Act 95 of 1998) and Regulations (HCPMA)*, and the *NHBC Technical Requirements at Erf 3126, Hartenbos* Western Cape Province. This development is referred to as **House Venter** in this report.

The original RFQ dated 21 February 2025 recorded structural defects in the roof structure, with special reference to the back Patio balcony roof, which area of defects constitutes the scope of investigation.

A site brief was held on 7 August 2025 to acquaint all parties with the defects followed by an official inspection held on 15 September 2025.

Documentation made available to **TechQ** are listed and elaborated on in **Section 1.3** below.

Section 2 of the report outlines the affected areas with notes taken during the investigation.

The concepts remedial works outlined in **Section 3** of this report are informed by the site inspections, review of architect drawings together with the assessment done towards the complaints raised by the Homeowner as recorded in the RFQ.

A concept design review discussion session was held with the NHBC on 10 October 2025, with relevant comments incorporated in this report.

In summary, the following concept remedial repair works are presented.

Section	Concept Remedial Actions – Drawing attached as Annexure A
<ul style="list-style-type: none">Patio balcony roof structure	<p><u>Re-construct Patio balcony roof structure</u></p> <ul style="list-style-type: none">Remove all existing roof covering of the Patio balcony roof structure on the outside of the building only.Supply and erect new timber roof trusses as detailed on the drawing attached as Annexure A.Finish roof off with new gypsum ceiling boards and strips. <p><u>Repair damaged roof flashing, waterproofing, ceiling boards and strips</u></p> <ul style="list-style-type: none">Repair all damaged roof ceiling boards, flashing, waterproofing and strips in the area as indicated on the drawing attached as Annexure A.


---- End of Executive Summary ----

1 PROJECT LOCALITY, SCOPE AND INFORMATION

1.1 Project Locality

Erf 3126, Hartenbos (House Venter) is located at No.51 Bloukrans Street, Hartenbos, within the boundaries of the **Mossel Bay Municipality** as show on the Figures below.

Site coordinates are **South: 34° 07' 20"** **East: 22° 06' 53"**



Project Location: House Venter

1.2 Scope of Work

1.2.1 Original RFQ scope of works

TechQ Development (Pty) Ltd was appointed by the **NHBRC** to conduct an **Investigation** towards structural and waterproofing defects of the property with the following specific deliverables.

- Investigate structural and waterproofing defects that have manifested at the above-mentioned home and classify them in terms of the Housing Consumer Protection Measures Act (Act 95 of 1998) and Regulations (HCPMA) and the NHBRC Technical Requirements.
- Structural defect to roof section.
- Determine the root causes of defects, report on the defects of the existing structure and provide remedial solutions and specifications including drawings where necessary.

Throughout the investigation and considerations of remedial works, special attention is drawn to **Chapter III** of the Act, clause 13(1)(b) – (i) “rectify major structural defects” and (ii) “deviation from plans or any deficiency related to design, workmanship or materials”.

1.2.2 Additional scope following site brief and site inspection

The main focus of the investigation is towards the defected metal roof section reported by the Homeowner, located on the outside Patio balcony area. No additional defects were highlighted at the site brief or during the investigation period.

1.3 Information Provided and Independent tests conducted

Information received from the NHBRC, Homeowner and design Architect involved in the planning and construction of the building, provided background to the building and affected area of investigation

1.3.1 Annexure B – Municipal approved Architect drawings

The original architect design drawings prepared by **SHAZCO Draughting** dated February 2020, approved in June 2020 is attached as **Annexure B**. Very limited detail is given on the architect drawings towards the investigation area, which was measured during the investigation period.

2 INVESTIGATION: DISCREPANCIES, NON-CONFORMANCES AND POSSIBLE ROOT CAUSES

Pictures related to the defected areas with brief comments are given below taken during the investigation. Remedial engineering concepts are elaborated on in **Section 3**.

2.1 Defected metal roof of Patio Balcony

The Homeowner reported that the external Patio balcony metal roof shows areas of settlement on the top and suspected the timber beam in support of the roof canopy to have deflected.

The picture album below provides images of the timber beam in support of the roof canopy, also roof flashings, ceiling boards and straps damaged on top of the metal roof.



Pic 01: Patio balcony roof construction.



Pic 02: Timber beam in support of roof structure.



Pic 03: Deflection in metal roof sheeting.



Pic 04: Damaged roof flashing and ceiling board elements.



3 ENGINEERING REMEDIAL SOLUTIONS AND RECOMMENDATIONS

Contributing factors towards the **possible route causes** resulting in the metal roof to deflect and timber beam not to function as intended were investigated to determine possible concept remedial works to the investigation area.


3.1 Reconstruct Patio balcony roof section

All indications are that the timber beam in support of the balcony roof assembly has deflected, or the 3 x anchor bolts used to fix the timber beam to the external building wall, may have come loose during windy and abnormal rain conditions.

The images below are graphical views of the remedial works towards balcony section of the roof, also detailed on the drawing attached as **Annexure A**.



DETAIL 1: TYPICAL TRUSS DETAIL - TRUSS 1
New Truss Design



DETAIL 2: NEW PATIO TRUSSES
Support beams and ceiling detail

3.2 Repair roof flashing, ceiling boards and straps

Evidence of damaged roof flashing, possible waterproofing defects and damaged ceiling boards with strips were located for approximately 3m along the chimney brickwork towards the centre of the building roof section as indicated on the drawing attached as **Annexure A**.

The damaged roof material to be removed and replaced with new elements to match existing.

Where waterproofing is damaged, these areas to be re-waterproofed and watertightness tests conducted to ensure no leaks to the roof.

3.3 Summary: Engineering Solutions

In summary, the following concept remedial repair works are presented.

Section	Concept Remedial Actions – Drawing attached as Annexure A
<ul style="list-style-type: none"> Patio balcony roof structure 	<p><u>Re-construct Patio balcony roof structure</u></p> <ul style="list-style-type: none"> Remove all existing roof covering of the Patio balcony roof structure on the outside of the building only. Supply and erect new timber roof trusses as detailed on the drawing attached as Annexure A. Finish roof off with new gypsum ceiling boards and strips. <p><u>Repair damaged roof flashing, waterproofing, ceiling boards and strips</u></p> <ul style="list-style-type: none"> Repair all damaged roof ceiling boards, flashing, waterproofing and strips in the area as indicated on the drawing attached as Annexure A.

4 RISKS & MITIGATION MEASURES

Qualifications, risks and possible sensitivity issues needs to be considered in performing the proposed remedial Works during the construction stage. The main objective of the Project is repair works as defined in **Section 3** above, however, the following aspects with mitigation proposals, need to be taken into consideration in the Risk Register of the Project.

Risks and mitigation measures

Nature of Risk	Risk	Mitigation
Site and Construction Risks	Abnormal rainfall and restricted working space	Proper scheduling of Works, being aware of the "critical path" items and implementing effective construction methodologies, Quality Assurance and Controls.
Limiting Factors	Decanting plan	Phased implementation of Works in accordance with proper planned decanting program.
Health and Safety	Delays and Fatal	Detailed OH&S plan compiled.
Quality Assurance	Construction Management	QA and QC Inspection procedures in place and approved
	Sub-standard materials	Quality tests and Agreements in place
OH&S and Environmental	Disturbance to environment, community and workers	Focus on the environment, building rubble disposals, air and noise pollution and disruption of day-to-day operations

--- End of Report ---